

RaceHub Version 4.0

Version 4.0.2

Released: December 18th, 2024

Bug fixes

Area	Description	ID
Miscellaneous	Fixed a bug in the RaceHub Service that caused excessive CPU usage. The RaceHub Service is no longer visible in Task View / Task Switcher.	2794

Version 4.0.1

Released: December 17th, 2024

New or changed functionality

Steering Wheel

Area	Description	ID
Display	Display support for more cars in Assetto Corsa.	2773

Bug fixes

Area	Description	ID
Miscellaneous	RaceHub had a memory leak that could increase the software's memory usage over time.	2597
Pedals	A phantom clutch could appear even though no clutch was connected.	2749
Pedals	The pedal calibration was sometimes not closed when completed.	2734 2703
Pedals and Steering Wheel	Improved the pedals and steering wheel import functionality. Sometimes the imported profile wasn't shown in the UI before the page was updated.	2707

Steering Wheel	Some idle mode effects on the steering wheel didn't turn off the LEDs as	-
	they should.	

Version 4.0.0

Released: June 21st, 2024

New or changed functionality

Wheelbase

Area	Description	ID
Torque	Increased max value on damping, friction, inertia, and cornering force assist. This allows you to add more of each effect if desired.	-
	Please note that your old values might have been changed. This ensures the wheelbase feeling doesn't change with the update.	
Torque	Increase resolution on the inertia, cornering force assist, and anti- oscillation sliders. This allows you to adjust the effect more precisely, moreover, the design aligns with the damping and friction sliders.	2620
	Please note that your old values might have been changed. This ensures the wheelbase feeling doesn't change with the update.	

RaceHub

Area	Description	ID
Steering Wheel	Support for Invicta steering wheel including 3 new dash layouts with	576
	support for different units.	1874
		2300
Steering Wheel	Support for SimHub.	1441
	 Layouts – requires Asetek SimSports Invicta steering wheel. 	
	Flag lights	
	Shift light	
	Please note that you'll need SimHub version 9.5.0 or newer to use this feature.	
Miscellaneous	Smaller user interface improvements.	2413
		2621

Bug fixes

Area	Description	ID
Torque	Cornering Force Assist has little or no effect in the games. Therefore, the maximum value has been increased giving you more possibilities to feel the setting.	2307
	Please note that your old Cornering Force Assist value might have been changed. This is to ensure that the wheelbase feeling doesn't change.	
Torque	Fixed how the basic/advanced toggle works.	2414
Shift Lights	Fixed an issue where shift lights didn't work as they should while playing iRacing.	2687 2702
Miscellaneous	USB communication optimizations.	2302
Miscellaneous	Fixed an issue where the pedal profile import didn't import all the settings.	2686
Miscellaneous	Fixed an issue where the steering wheel profile import wasn't loaded properly.	2700 2357
Miscellaneous	Fixed an issue where you, in rare cases, couldn't save your wheelbase settings.	2627

-